The solve method list for electro problems of CNC fully

Problem	Reason	Solve method
1. The	①PLC not working.	① Check the power supply
motor	②Overload protection action.③ The oil level of oil tank	and the front transformer and fuse of PLC.
can't start	lower than sensor. ④ The air pressure of safe	② Check the working current and the loading of motor.
	pin is low to alarm.	③ Rise the oil level to the
	⑤ The oil temperature is	control range of sensor.
	too hot>60°C 。	(4) Check the system pressure
	⁽⁶⁾ Oil temperature too low	and check is there air leak or
	< 20°C 。	not.
	The fuse of main return	(5) Check the working
	road failure.	condition of the cooling
	[®] The air switch not close	pump.
	or tripping.	6 Check the working
	(9) The power supply of	
	PLC is short circuit.	device.
		(7)Check and change.
		(a) Close the air switch.
		(9) Check the PLC and the
		outer wire line.
2. The fuse	①The loading short circuit	(1) Check the loading.
failure	or overloading.	
lanure		② Screw tight the terminal
	⁽²⁾ Poor contact of fuse.	screw.

hydraulic die forging hammer

3.The	① Poor contact of coil	① Screw tight the terminal
aantaatar	terminal line.	screw.
contactor	② Is there objects embed	
shock strong	in the attracting iron	(2) Remove it.
when closed	core.	
when closed	③ The short circuit ring of iron core come off or not.	3)Check the contactor
	1) The wire connect of	1 Pight the wire connect
4. The	temperature gauge not	1) Right the whe connect.
common	right.	
11 0	ingite.	② Check the temperature
problem of		course and conversion medule
temperature		gauge and conversion module.
measuremen		
measuremen		
t system		
5.system	① Connection of pressure	① Right connection.
fault of	sensor is wrong.	(2) Check pressure sensor and
testing		convertion die is Ok or not.
pressure		
6.system	(1) approach switch of	① right connection. Check
faulit of	hammer head is not work.	whether approach swich loose
ejection	2 magnetic valve of	or fault.
	ejection part is blocked.	^② Check, change.
7.circle	① overcurrent protection	(1) check motor work and load
purmp is	operation	condition.
not work		② check and change filter

	2 Differential pressure	element.
	switch operation.	
8.hitting	①not in running state	①put the key in running state
valve is not	2 approach switch of	② check approach switch
work.	hammer head is not work.	connection and installation.
	③ approach switch of	③ check working condition of
	safety pin is not work.	safety pin and approach switch
		connection and installation.
8.others	① under adjustment	(1) approach switch of safety pin
	status, slow down valve is	is not work, chech whether
	not work.	mechanical blocked in safety
	2 motor can't be started	pin, air pressure low,
		connection of approach switch.
		② the key is not in adjustment
		status.

Attention in operation and maintainance:

- A. When motor working, don't operate circuit breaker of electric cabinet,otherwise it will bring load operation, electrical components burnout.
- B. Please cutting all of electricity when checking.